		/		/.			Moc Market Marke	over		<b>&gt;</b>		ني / د	, / <u>«</u>
Tra	ansfer Formula	Co C	NA CANAL STATE OF THE STATE OF	Silitate Sil	Clon	A <sub>o</sub> c	No.	Milor	O I I I I I I I I I I I I I I I I I I I	QUE	,	7/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2	Jirio O
How Many Colors Are in Your Art?													
	1 - 3 Spot Colors	<b>~</b>		<b>~</b>	~	~	~	~		~	~	~	~
	Full Color (CMYK)	~	~	~			~	~	~				
What Kind of Fabric Are You Decorating?													
	100% Cotton	<b>~</b>	~	<b>~</b>	~	<b>~</b>			~	~	~	~	~
100% Polyester			~		~	~			~		~	~	
Cotton/Poly		<b>~</b>	~	~	~	~			~	~	~	~	~
Tri-Blends			~		~				~			~	
Spandex/ Lycra									~		~		
Nylon								~					
Non Woven			~				~		~				
Application Temp		350	300.	365	325	325	270 <sup>°</sup>	300.	320	350	325	325	375 <sup>°</sup>
		V	/hat Size	e Are Yo	ur Desig	ns and	How Ma	ny Do y	ou Need	l?			
Single Image Options													
Minimum Order Quantity		1		36	36	1	100	1	36	1	1	1	1
Sheet Sizes	9" x 12.75"	<b>~</b>		~	~	<b>~</b>	~	~	~	~	~	~	~
	12" x 12"	<b>~</b>		~	~	<b>~</b>	~	~	~	~	~	~	~
	17" x 4"	<b>~</b>									~	~	~
					Gang	Sheet O	otions						
Minimum Order Quantity		1	1	8	8	8	8	8	8	8	8	8	8
	4" x 6"	<b>~</b>		<b>~</b>	~	~	~	~	~	~	<b>~</b>	<b>~</b>	~
	6" x 9"	<b>~</b>		~	<b>~</b>	~	~	~	~	~	~	~	~
# S	9" x 12.75"	<b>~</b>		~	<b>~</b>	~	~	~	~	~	~	~	~
Sheet Sizes	12" x 12"	<b>~</b>		~	<b>~</b>	~	~	~	~	~	~	~	~
SO	12.75" x 19"	<b>~</b>		~	<b>~</b>	~	~	~	~	~	~	~	~
	22" x 12"		<b>~</b>										
	22" x 24"		<b>~</b>										

## Which Transfer?

Find the best transfer for your next project!

We're committed to supporting you through every apparel decoration project. That's why we offer 12 different transfer formulas. Use the guide below to help you find the best transfer, whatever the need.

